Annexure D

BUILDING SAFETY CERTIFICATE

No.

Dated: .....

It is certified that the existing building Little Flower H.S. School (name of the building or premises) at .....Deendayal Upadhyaya Nagar Raipur..... (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	G+3	G+2	G+2	G+1	G+3	

The building is owned/occupied by...Little Flower Hr. Sec. School (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Raipur Municipal Corporation (Name of Department/ Govt.) on..18/10/2024 (date of inspection) in the presence of Mr. R. L. Chandra (Principal) L.F.S (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from..04/11/2024 for a period of .....03..... years in accordance with rule and subject to compliance of the specific conditions as appended.

1.
2.
3.
4.

Issued on ..04/11/2024 at ..Raipur..... by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal

कार्यपालन अभियंता
जोन क्र. 5
नगर पालिक निगम, रायपुर

Name : L.M.P. Singh

Designation : E.E.R.M.C.

Name & Address of Department/ Office:

(L.M.P. Singh)

66 | Page

Chandra
PRINCIPAL
Little Flower Higher Secondary School
Sec.-2, Deendayal Upadhyaya Nagar
Raipur (C. G.) 492001